

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Sutter Maintenance Yard Nelson Bend

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River West Levee - Nelson Bend		0.50	03/24/2020 03/24/2020	Sterling York

LM Start		Rating **	A	Issue No.	9
LM End		Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_ST0006_01_s_2014_9				
Comment Code					
Inspector Comment					
Sutter Maintenance Yard has copies of the O&M manuals.					

No Photos

LM Start		Rating **	A	Issue No.	10
LM End		Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_ST0006_01_s_2014_10				
Comment Code					
Inspector Comment					
Sutter Maintenance Yard has flood fight supplies on hand at their equipment yard.					

No Photos

LM Start		Rating **	A	Issue No.	11
LM End		Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_ST0006_01_s_2014_11				
Comment Code					
Inspector Comment					
Sutter Maintenance Yard has attends flood fight training at their yard yearly.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Sutter Maintenance Yard Nelson Bend

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River West Levee - Nelson Bend		0.50	03/24/2020 03/24/2020	Sterling York

LM Start	0.01	Rating **	U	Issue No.	2
LM End	0.50	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.887015 °	38.880306 °
				-121.614693 °	-121.614151 °
DWR ID	DWR_ST0006_01_f_2019_2				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
This levee is privately owned and not maintained by the LMA. The vegetation has not been maintained, Spring 2020.					

Photo 1 of 1 : SP_2020_ST0006_471_2_20200401_00011.jpg



View looking downstream landside at the annual vegetation that is not maintained, Spring 2020.

LM Start	0.01	Rating **	U	Issue No.	15
LM End	0.50	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.887015 °	38.880306 °
				-121.614693 °	-121.614151 °
DWR ID	DWR_ST0006_01_f_2019_15				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
This levee is privately owned and not maintained by the LMA. The vegetation has not been maintained, Spring 2020.					

Photo 1 of 1 : SP_2020_ST0006_471_15_20200401_00010.jpg



View looking downstream waterside at the annual vegetation that is not maintained, Spring 2020.

LM Start	0.06	Rating **	M	Issue No.	4
LM End	0.06	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.886277 °	38.886277 °
				-121.615129 °	-121.615129 °
DWR ID	DWR_ST0006_01_s_2012_4				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Elderberries are partially blocking visibility.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Sutter Maintenance Yard Nelson Bend

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River West Levee - Nelson Bend		0.50	03/24/2020 03/24/2020	Sterling York

LM Start	0.13	Rating **	U	Issue No.	1
LM End	0.50	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.885396 °	38.880295 °
				-121.615595 °	-121.614147 °
DWR ID	DWR_ST0006_01_f_2017_1				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					
Trim up the trees to 5 feet above the ground for access and visibility, Spring 2020.					


Photo 1 of 1 : SP_2020_ST0006_471_1_20200227_00001.jpg



View looking downstream waterside of the over growth of trees.

LM Start	0.13	Rating **	U	Issue No.	3
LM End	0.50	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.885396 °	38.880295 °
				-121.615595 °	-121.614147 °
DWR ID	DWR_ST0006_01_f_2017_3				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					
Trim up the trees to 5 feet above the ground for access and visibility, Spring 2020.					

Photo 1 of 1 : SP_2020_ST0006_471_3_20200227_00003.jpg



View looking downstream landside of the over growth of trees.

LM Start	0.15	Rating **	M	Issue No.	5
LM End	0.15	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.885100 °	38.885100 °
				-121.615722 °	-121.615722 °
DWR ID	DWR_ST0006_01_s_2012_5				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Elderberries are partially blocking visibility.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Sutter Maintenance Yard Nelson Bend

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River West Levee - Nelson Bend		0.50	03/24/2020 03/24/2020	Sterling York

LM Start	0.16	Rating **	M	Issue No.	12
LM End	0.16	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.884946 °	38.884946 °
				-121.615761 °	-121.615761 °
DWR ID	DWR_ST0006_01_s_2015_12				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Elderberries are partially blocking visibility.					

No Photos

LM Start	0.18	Rating **	M	Issue No.	13
LM End	0.18	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.884577 °	38.884577 °
				-121.615761 °	-121.615761 °
DWR ID	DWR_ST0006_01_s_2015_13				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Elderberries are partially blocking visibility.					

No Photos

LM Start	0.21	Rating **	M	Issue No.	14
LM End	0.21	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.884151 °	38.884151 °
				-121.615732 °	-121.615732 °
DWR ID	DWR_ST0006_01_s_2015_14				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Elderberries are partially blocking visibility.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Sutter Maintenance Yard Nelson Bend

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River West Levee - Nelson Bend		0.50	03/24/2020 03/24/2020	Sterling York

LM Start	0.34	Rating **	M	Issue No.	6
LM End	0.34	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.882398 °	38.882398 °
				-121.614966 °	-121.614966 °
DWR ID	DWR_ST0006_01_s_2012_6				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Elderberries are partially blocking visibility.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---